



225180724

232450042

### Gestão de Motor

### Sensores de Temperatura do Líquido de Refrigeração



<p>06.330082</p>   <p><b>SENS TEMP LÍQ REFRI ALFA ROMEO, FIAT, LANCIA, SEAT</b> 2101-3808-600, 4067872</p>	<p>06.330085</p>   <p><b>32230 - SENS TEMP LÍQ REFRI DAEWOO, OPEL, SAAB</b> 3439088, 4772216</p>	<p>06.330086</p>   <p><b>31280 - SENS TEMP LÍQ REFRI CITROEN, FIAT, PEUGEOT</b> 315168056RS, 2990857</p>	<p>06.330094</p>   <p><b>31490 - SENS TEMP LÍQ REFRI ROVER</b> 623050, GTR101</p>
<p>06.330095</p>   <p><b>32350 - SENS TEMP LÍQ REFRI HONDA, ROVER, SUZUKI</b> EDU1256, GTR184</p>	<p>06.330097</p>   <p><b>32270 - SENS TEMP LÍQ REFRI BMW, LAND ROVER</b> 12621710511, STC 2253</p>	<p>06.330100</p>   <p><b>31570 - SENS TEMP LÍQ REFRI DAIHATSU</b> 94650-32500, 94650-32510</p>	<p>06.330103</p>   <p><b>33620 - SENS TEMP LÍQ REFRI AUDI, FORD, SEAT</b> 251919501A, 251919501D</p>
<p>06.330104</p>   <p><b>SENS TEMP LÍQ REFRI DAEWOO, MERCEDES-BENZ, VW</b> 0025422517, 0055421017</p>	<p>06.330107</p>   <p><b>33330 - SENS TEMP LÍQ REFRI ALFA ROMEO, CHEVROLET</b> 25036898, 96181508</p>	<p>06.330108</p>   <p><b>32370 - SENS TEMP LÍQ REFRI RENAULT, VOLVO</b> 3545031-1, 9186486-8</p>	<p>06.330112</p>   <p><b>31680 - SENS TEMP LÍQ REFRI NISSAN</b> 25080-70J00</p>
<p>06.330116</p>   <p><b>3301 - SENS TEMP LÍQ REFRI BMW, FIAT, FORD, HONDA, VW</b> 5972332, 98424793</p>	<p>06.330117</p>   <p><b>33340 - SENS TEMP LÍQ REFRI DAEWOO, LANCIA, OPEL, FIAT</b> 15326386, 25036979</p>	<p>06.330118</p>   <p><b>32330 - SENS TEMP LÍQ REFRI MERCEDES-BENZ</b> 0055450324, 55450324</p>	<p>06.330120</p>   <p><b>33200 - SENS TEMP LÍQ REFRI FIAT, FORD, LANCIA, OPEL</b> 700021, 1639283</p>
<p>06.330121</p>   <p><b>33600 - SENS TEMP LÍQ REFRI BMW, FIAT, FORD, LANCIA</b> 6081220, 6081224</p>	<p>06.330122</p>   <p><b>33120 - SENS TEMP LÍQ REFRI CITROEN, FIAT, LANCIA, PEUGEOT</b> 700015, 9613147080</p>	<p>06.330124</p>   <p><b>33065 - SENS TEMP LÍQ REFRI ALFA ROMEO, FIAT</b> 46449499, 60576529</p>	<p>06.330128</p>   <p><b>33650 - SENS TEMP LÍQ REFRI SEAT, SKODA, VW</b> 357919501, 357919501B</p>
<p>06.330130</p>   <p><b>33250 - SENS TEMP LÍQ REFRI FORD, MAZDA, MINI, SUZUKI, VW</b> 30874172, 8653103</p>	<p>06.330132</p>   <p><b>33060 - SENS TEMP LÍQ REFRI OPEL, RENAULT, VOLVO</b> 3344169, 3345511</p>	<p>06.330134</p>   <p><b>SENS TEMP LÍQ REFRI CITROEN, FIAT, LANCIA, PEUGEOT</b> 133847, 133878</p>	<p>06.330137</p>   <p><b>33485 - SENS TEMP LÍQ REFRI CITROEN, FIAT, HONDA, VW</b> 90542063, 500382599</p>



















































225180724

232450042

### Gestão de Motor

### Sensores de Temperatura do Líquido de Refrigeração



<p>06.330138</p>   <p>33724 - SENS TEMP LÍQ REFRI DACIA, NISSAN 4408333, 4502758</p>	<p>06.330141</p>   <p>33781 - SENS TEMP LÍQ REFRI AUDI, FORD, SEAT 078919501C</p>	<p>06.330142</p>   <p>33700 - SENS TEMP LÍQ REFRI FIAT, LANCIA 1338040, 6338023</p>	<p>06.330143</p>   <p>33720 - SENS TEMP LÍQ REFRI ALFA ROMEO, FIAT 46474713, 60814402</p>
<p>06.330144</p>   <p>33425 - SENS TEMP LÍQ REFRI FORD, MAZDA 1E00-18510, C201-18140-Z01</p>	<p>06.330147</p>   <p>34110 - SENS TEMP LÍQ REFRI CITROEN, FIAT 9601842280, 9617916180</p>	<p>06.330149</p>   <p>SENS TEMP LÍQ REFRI 0065459124, A0065459124</p>	<p>06.330151</p>   <p>34330 - SENS TEMP LÍQ REFRI AUDI, FORD, VW 1669990, 95VW8B607LA</p>
<p>06.330153</p>   <p>34350 - SENS TEMP LÍQ REFRI OPEL, RENAULT M810074, 308100742</p>	<p>06.330154</p>   <p>34440 - SENS TEMP LÍQ REFRI CITROEN, PEUGEOT 024283</p>	<p>06.330286</p>   <p>SENS TEMP LÍQ REFRI AUDI, FORD 0025420718, 1669965</p>	<p>06.330287</p>   <p>33640 - SENS TEMP LÍQ REFRI FORD, SEAT 357919 501A, 1331294</p>
<p>06.330309</p>   <p>35480 - SENS TEMP LÍQ REFRI AUDI, VW 035919369S, 053919369A</p>	<p>06.330496</p>   <p>33783 - SENS TEMP LÍQ REFRI AUDI, FORD, SEAT 1100619, 059919501A</p>	<p>06.330497</p>   <p>33782 - SENS TEMP LÍQ REFRI AUDI, SEAT 059919501, 078919501B</p>	<p>06.330500</p>   <p>33782 - SENS TEMP LÍQ REFRI AUDI, SEAT 059919501, 078919501B</p>
<p>06.330502</p>   <p>33706 - SENS TEMP LÍQ REFRI CITROEN, FIAT 9632562080, 1204700</p>	<p>06.330509</p>   <p>33680 - SENS TEMP LÍQ REFRI ALFA ROMEO, FIAT 55203964, 12 992 783</p>	<p>06.330530</p>   <p>33595 - SENS TEMP LÍQ REFRI LAND ROVER MEK100060L, GTR 206</p>	<p>06.330546</p>   <p>33784 - SENS TEMP LÍQ REFRI AUDI, FORD MN980152, 1100736</p>
<p>06.330551</p>   <p>33795 - SENS TEMP LÍQ REFRI CITROEN, FIAT 133897, 9631000880</p>	<p>06.330552</p>   <p>33707 - SENS TEMP LÍQ REFRI CITROEN, MINI 13 627535068, 1338F3</p>	<p>06.330555</p>   <p>33760 - SENS TEMP LÍQ REFRI FIAT, LANCIA 46414596</p>	<p>06.330558</p>   <p>SENS TEMP LÍQ REFRI DACIA, NISSAN, OPEL 4431529, 7700110664</p>



### Gestão de Motor

### Sensores de Temperatura do Líquido de Refrigeração



<p>06.330562</p>   <p>33800 - SENS TEMP LÍQ REFRI HYUNDAI MD069879, 39220-21310</p>	<p>06.330574</p>   <p>SENS TEMP LÍQ REFRI HYUNDAI 10105810, 39230-26600</p>	<p>06.330582</p>   <p>SENS TEMP LÍQ REFRI CHEVROLET, DAEWOO 39220-02500, 39220-02520</p>	<p>06.330583</p>   <p>SENS TEMP LÍQ REFRI FORD, NISSAN 0K011-18840, 22630-51E00</p>
<p>06.330584</p>   <p>33746 - SENS TEMP LÍQ REFRI FORD 3857955, 5040463</p>	<p>06.330585</p>   <p>33745 - SENS TEMP LÍQ REFRI CITROEN, FORD 1109340, U202-18840</p>	<p>06.330588</p>   <p>33792 - SENS TEMP LÍQ REFRI CITROEN, FIAT 133810, 9603324880</p>	<p>06.330605</p>   <p>SENS TEMP LÍQ REFRI FORD 3936774, F77F10884BB</p>
<p>06.330606</p>   <p>SENS TEMP LÍQ REFRI FORD 3999215, F83F10884AA</p>	<p>06.330619</p>   <p>33310 - SENS TEMP LÍQ REFRI CHEVROLET MD177572, 30874182</p>	<p>06.330624</p>   <p>33705 - SENS TEMP LÍQ REFRI CITROEN, FIAT 0986280404, E10609836PS</p>	<p>06.330635</p>   <p>SENS TEMP LÍQ REFRI KIA, HYUNDAI 0K50F-18840, 39220-2X100</p>
<p>06.330636</p>   <p>33785 - SENS TEMP LÍQ REFRI AUDI, VW 700025, 058919501A</p>	<p>06.330639</p>   <p>34400 - SENS TEMP LÍQ REFRI CITROEN, FIAT 133843, 9620384780</p>	<p>06.330641</p>   <p>32540 - SENS TEMP LÍQ REFRI ALFA ROMEO, FIAT 7735919</p>	<p>06.330642</p>   <p>33350 - SENS TEMP LÍQ REFRI HYUNDAI, KIA MD149338, 39220-35510</p>
<p>06.330643</p>   <p>33155 - SENS TEMP LÍQ REFRI BMW, LAND ROVER 12621433076, MEK000030L</p>	<p>06.330647</p>   <p>32710 - SENS TEMP LÍQ REFRI MERCEDES-BENZ A2C85403000, MN960160</p>	<p>06.330656</p>   <p>33150 - SENS TEMP LÍQ REFRI FIAT, LANCIA 0280130066, 7669143</p>	<p>06.330659</p>   <p>SENS TEMP LÍQ REFRI JEEP, CHRYSLER 56004815</p>
<p>06.330661</p>   <p>SENS TEMP LÍQ REFRI HYUNDAI 94650-42050, 94650-42051</p>	<p>06.330663</p>   <p>SENS TEMP LÍQ REFRI HYUNDAI 39230-42000</p>	<p>06.330665</p>   <p>33357 - SENS TEMP LÍQ REFRI CHEVROLET 39220-02510</p>	<p>06.330692</p>   <p>33810 - SENS TEMP LÍQ REFRI DACIA, MITSUBISHI 91 10 578, M883623</p>



225180724 232450042

Gestão de Motor

Sensores de Temperatura do Líquido de Refrigeração



<p>06.330693</p>   <p>33850 - SENS TEMP LÍQ REFRÍ FIAT, LANCIA 46824133, 71716685</p>	<p>06.330709</p>   <p>SENS TEMP LÍQ REFRÍ CITROEN, PEUGEOT 133866</p>	<p>06.330742</p>   <p>33790 - SENS TEMP LÍQ REFRÍ CITROEN, FIAT 9633518580, 1338C0</p>	<p>06.330757</p>   <p>SENS TEMP LÍQ REFRÍ ALFA ROMEO A2C53312552, A2C83276100</p>
<p>06.330759</p>   <p>33460 - SENS TEMP LÍQ REFRÍ FORD, NISSAN 0280130071, 0280130081</p>	<p>06.330770</p>   <p>SENS TEMP LÍQ REFRÍ SUZUKI, FORD, NISSAN 13650-54G00-000</p>	<p>06.330774</p>   <p>33035 - SENS TEMP LÍQ REFRÍ MERCEDES-BENZ 0005426218, 0051532328</p>	<p>06.330778</p>   <p>33295 - SENS TEMP LÍQ REFRÍ BMW, LAND ROVER 170 3993, 13621703993</p>
<p>06.330791</p>   <p>32706 - SENS TEMP LÍQ REFRÍ MERCEDES-BENZ 0009050600, 0009056102</p>	<p>06.330792</p>   <p>L = 56.5 SENS TEMP LÍQ REFRÍ FORD, JAGUAR 1121670, 1338 F0</p>	<p>06.330803</p>   <p>SENS TEMP LÍQ REFRÍ HONDA, ROVER 5-86202-847-0, 37870-PJ7-003</p>	<p>06.330810</p>   <p>SENS TEMP LÍQ REFRÍ FORD 1079267, 1552452</p>
<p>06.330820</p>   <p>SENS TEMP LÍQ REFRÍ NISSAN, CITROEN 1452490, 16970-BN700</p>	<p>06.330851</p>   <p>32510 - SENS TEMP LÍQ REFRÍ MERCEDES 700050, 0085425617</p>	<p>06.330852</p>   <p>SENS TEMP LÍQ REFRÍ FORD, SUZUKI 6107551, 34850-78E00-000</p>	<p>06.330854</p>   <p>SENS TEMP LÍQ REFRÍ VOLVO 9125463</p>
<p>06.330857</p>   <p>33890 - SENS TEMP LÍQ REFRÍ BMW, MINI 13627797957, 7797957</p>	<p>06.330859</p>   <p>SENS TEMP LÍQ REFRÍ LANCIA, FIAT 7083932, 71736835</p>	<p>06.330862</p>   <p>32470 - SENS TEMP LÍQ REFRÍ LAND ROVER AMR 1425</p>	<p>06.330864</p>   <p>33600 - SENS TEMP LÍQ REFRÍ BMW, CITROEN, FIAT, SAAB 028013055, 90487859</p>
<p>06.330869</p>   <p>33335 - SENS TEMP LÍQ REFRÍ CHRYSLER, JEEP 5269870AB, 13621486698</p>	<p>06.330870</p>   <p>SENS TEMP LÍQ REFRÍ HONDA 179700-0500, 37870-RTA-005</p>	<p>06.330885</p>   <p>36540 - SENS TEMP LÍQ REFRÍ TOYOTA 071400-5520, 89428-06010</p>	<p>06.330922</p>   <p>SENS TEMP LÍQ NISSAN, RENAULT 22630-00Q1P, 226300007R</p>





225180724

232450042

### Gestão de Motor

### Sensores de Temperatura do Líquido de Refrigeração



<p>06.330929</p>  <p>SENS TEMP LÍQ REFRI FIAT, LANCIA 71718201</p>	<p>06.330951</p>  <p>SENS TEMP LÍQ REFRI VW 074919501</p>	<p>06.330971</p>  <p>SENS TEMP LÍQ REFRI AUDI, JEEP, SEAT 5033378AA, K5033378AA</p>	<p>06.350401</p>  <p>SENS TEMP LÍQ REFRI DACIA, MITSUBISHI, NISSAN, RENAULT 9110578, 30883623</p>
<p>09.30160</p>  <p>SENSOR TEMP LÍQ REFRI EBRO 534841040000</p>	<p>09.30260</p>  <p>SENS TEMP LÍQ REFRI CITROEN, FIAT, PEUGEOT 4254, 315031.01, 315131</p>	<p>09.30300</p>  <p>SENSOR TEMP LÍQ REFRI MERCEDES 309065, 323-801-001-054</p>	<p>09.31020</p>  <p>SENS TEMP LÍQ REFRI CITROEN, FIAT 534841130000, 510078890020</p>
<p>09.31110</p>  <p>SENSOR TEMP LÍQ REFRI JAGUAR, OPEL, ROVER 534843150000, 323.801/001/001</p>	<p>09.31140</p>  <p>SENSOR TEMP LÍQ REFRI ALFA ROMEO, FIAT, SEAT 8214, 510099858501</p>	<p>09.31190</p>  <p>SENSOR TEMP LÍQ REFRI ROVER SU6,7954935, GTR104</p>	<p>09.31200</p>  <p>SENSOR TEMP LÍQ REFRI ROVER GTR 109, GTR 106</p>
<p>09.31210</p>  <p>SENSOR TEMP LÍQ REFRI JAGUAR, ROVER GTR 110, GTR 108</p>	<p>09.31220</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT 534803540000, 1020</p>	<p>09.31270</p>  <p>SENSOR TEMP LÍQ REFRI FORD 1784077, C4AH10884</p>	<p>09.31280</p>  <p>SENSOR TEMP LÍQ REFRI PEUGEOT 510031516805, 101216</p>
<p>09.31290</p>  <p>SENSOR TEMP LÍQ REFRI BMW, SKODA ST 003, 323-801-001-006</p>	<p>09.31310</p>  <p>SENSOR TEMP LÍQ REFRI DAIHATSU TS-65, 83420-20011</p>	<p>09.31330</p>  <p>SENSOR TEMP LÍQ REFRI LEXUX, TOYOTA, HYUNDAI 6PT009107-631, 94650-11110</p>	<p>09.31360</p>  <p>SENSOR TEMP LÍQ REFRI VOLVO 323.804/004/004, 460191</p>
<p>09.31370</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN 6PT009107-171, 101821</p>	<p>09.31380</p>  <p>SENSOR TEMP LÍQ REFRI NISSAN 25080-Y9700, 78200001-0</p>	<p>09.31400</p>  <p>SENSOR TEMP LÍQ REFRI NISSAN 335443.01, 25080-G9600</p>	<p>09.31460</p>  <p>SENSOR TEMP LÍQ REFRI ALFA ROMEO 510099700001, 5174,091038.01</p>



225180724

232450042

### Gestão de Motor

### Sensores de Temperatura do Líquido de Refrigeração



<p>09.31490</p>  <p>SENSOR TEMP LÍQ REFRI ROVER GTR 101, SU 7,7 954 972</p>	<p>09.3152</p>  <p>SENSOR TEMP LÍQ REFRI FORD, NISSAN 25080-9F900, 1953639</p>	<p>09.31570</p>  <p>SENSOR TEMP LÍQ REFRI DAIHATSU, HYUNDAI 6PT009107-651, 83420-16020</p>	<p>09.31580</p>  <p>SENSOR TEMP LÍQ REFRI INFINITI, NISSAN 6PT009107-221, 25080-89903</p>
<p>09.31590</p>  <p>SENSOR TEMP LÍQ REFRI FIAT 116596489902, 6PT009107-621</p>	<p>09.31600</p>  <p>SENSOR TEMP LÍQ REFRI ALFA ROMEO, FIAT 101.9195.050, 7588856</p>	<p>09.31610</p>  <p>SENSOR TEMP LÍQ REFRI FORD, SKODA, SEAT 6PT 009107-691, 323.801/016/006</p>	<p>09.31620</p>  <p>SENSOR TEMP LÍQ REFRI ROVER GTR120, AAU1115</p>
<p>09.31630</p>  <p>SENSOR TEMP LÍQ REFRI MARUTI 96067370,96052069</p>	<p>09.31650</p>  <p>SENSOR TEMP LÍQ REFRI INFINITI, NISSAN TS-391,TS-391T</p>	<p>09.31670</p>  <p>SENSOR TEMP LÍQ REFRI SUZUKI 34850-82012</p>	<p>09.32010</p>  <p>SENSOR TEMP LÍQ REFRI FORD 6PT009107-381, 0824121100, ST051</p>
<p>09.32020</p>  <p>SENSOR TEMP LÍQ REFRI FORD, MAZDA 1E07-18-760, 6145142</p>	<p>09.32040</p>  <p>SENSOR TEMP LÍQ REFRI FORD 6PT 009107-331, 6145143</p>	<p>09.32070</p>  <p>SENSOR TEMP LÍQ REFRI CHEVROLET 6PT 009107-181, 323-801-005-001</p>	<p>09.32080</p>  <p>SENSOR TEMP LÍQ REFRI FORD 534861020000, GTR 114</p>
<p>09.32090</p>  <p>SENSOR TEMP LÍQ REFRI VW 323.804/002/001</p>	<p>09.3210</p>  <p>SENSOR TEMP LÍQ REFRI VOLKSWAGEN, VOLVO ST 038, 0824121084, 323-804-003-006</p>	<p>09.32110</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, SEAT, VOLKSWAGEN 323.801/016/002, 323.804/006/005</p>	<p>09.32150</p>  <p>SENSOR TEMP LÍQ REFRI NISSAN 25080-89900, 25251-37700</p>
<p>09.32160</p>  <p>SENSOR TEMP LÍQ REFRI DAIHATSU 071500-0430, 0824121085</p>	<p>09.32170</p>  <p>SENSOR TEMP LÍQ REFRI MAZDA 6PT 009107-201, SWE-2093</p>	<p>09.32190</p>  <p>SENSOR TEMP LÍQ REFRI FORD 6PT 009107-231, 6136366</p>	<p>09.32210</p>  <p>SENSOR TEMP LÍQ REFRI ISUZU, OPEL, VAUXHALL 1338505, 8-94235-691-0</p>



225180724

232450042

### Gestão de Motor

### Sensores de Temperatura do Líquido de Refrigeração



<p>09.32220</p>  <p>SENSOR TEMP LÍQ REFRI DAEWOO, PUCH 323-801-020-002D, 6PT009107-251</p>	<p>09.32230</p>  <p>SENSOR TEMP LÍQ REFRI DAEWOO, OPEL, SAAB 323-804-015-001, 6PT 009107-161</p>	<p>09.32240</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT 7.3094, 335014.01</p>	<p>09.32250</p>  <p>SENSOR TEMP LÍQ REFRI MERCEDES 0280130035, 8.175.05</p>
<p>09.32275</p>  <p>SENSOR TEMP LÍQ REFRI BMW 1404699,12611404699</p>	<p>09.32290</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, PEUGEOT 337353.02, 6PT 009107-681</p>	<p>09.32330</p>  <p>SENSOR TEMP LÍQ REFRI MERCEDES 323.801/015/001, 6PT 009107-371</p>	<p>09.32350</p>  <p>SENSOR TEMP LÍQ REFRI DAIHATSU 6PT009107-641, GTR 141</p>
<p>09.32370</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT, VOLVO 6PT 009107-281, 9186486</p>	<p>09.32425</p>  <p>SENSOR TEMP LÍQ REFRI VOLVO 9125463, TX-113</p>	<p>09.32470</p>  <p>SENSOR TEMP LÍQ REFRI LAND ROVER, MG, ROVER TS-559, AMR1425</p>	<p>09.32490</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT, VOLVO 6PT 009107-741, 77 00 808 951</p>
<p>09.32510</p>  <p>SENSOR TEMP LÍQ REFRI MERCEDES 0824121026, 0824121058</p>	<p>09.32520</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT, ROVER GTR 198</p>	<p>09.32540</p>  <p>SENSOR TEMP LÍQ REFRI ALFA ROMEO, LANCIA, FIAT ST 058, 08241121107</p>	<p>09.32560</p>  <p>SENSOR TEMP LÍQ REFRI BMW 323.805/034/001, 6PT 009107-471</p>
<p>09.32570</p>  <p>SENSOR TEMP LÍQ REFRI BMW 6PT 009107-311, GTR 179</p>	<p>09.32580</p>  <p>SENSOR TEMP LÍQ REFRI MERCEDES 6PT 009107-391, 008 5424517</p>	<p>09.32600</p>  <p>SENSOR TEMP LÍQ REFRI MITSUBISHI, OPEL 6PT009 107-601,6PT009107-601</p>	<p>09.32640</p>  <p>SENSOR TEMP LÍQ REFRI TOYOTA, VW J8342020030, 83420-16040</p>
<p>09.32650</p>  <p>SENSOR TEMP LÍQ REFRI TOYOTA, LEXUS</p>	<p>09.32710</p>  <p>SENSOR TEMP LÍQ REFRI MERCEDES-BENZ, SMART 323.805/043/001, MN-960160</p>	<p>09.32730</p>  <p>SENSOR TEMP LÍQ REFRI LAND ROVER ERR6397</p>	<p>09.33010</p>  <p>SENSOR TEMP LÍQ REFRI BMW, CITROEN, FIAT 0280130077, 6PT009107-361</p>



225180724

232450042

### Gestão de Motor

### Sensores de Temperatura do Líquido de Refrigeração



<p>09.33020</p>  <p>SENSOR TEMP LÍQ REFRI ALFA ROMEO 0280130023, 96060084</p>	<p>09.33030</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, BMW, FORD, SEAT 0 280130037, 6PT009107-351</p>	<p>09.33040</p>  <p>SENSOR TEMP LÍQ REFRI NISSAN 22630-D9701, 22630-D9702</p>	<p>09.33050</p>  <p>SENSOR TEMP LÍQ REFRI AUSTIN, MG, ROVER GTR 134, RTC 5522</p>
<p>09.33060</p>  <p>SENSOR TEMP LÍQ REFRI ALPINE, OPEL, RENAULT S101430001, 6PT 009 309-301</p>	<p>09.33065</p>  <p>SENSOR TEMP LÍQ REFRI ALFA ROMEO, FIAT 00402.01, 7.3157</p>	<p>09.33070</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN 171925011020, 700014</p>	<p>09.33080</p>  <p>SENSOR TEMP LÍQ REFRI CHRYSLER, NISSAN 0280130064, 0824121115</p>
<p>09.33090</p>  <p>SENSOR TEMP LÍQ REFRI ALFA ROMEO, FERRARI 0 280130069, 6PT009107-501</p>	<p>09.33100</p>  <p>SENSOR TEMP LÍQ REFRI FORD 6PT009 309-091, 7.3156</p>	<p>09.33110</p>  <p>SENSOR TEMP LÍQ REFRI INFINITI, NISSAN 0280130072, 6PT009107-531</p>	<p>09.33120</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, FIAT, LANCIA 171925011010, 700015</p>
<p>09.33130</p>  <p>SENSOR TEMP LÍQ REFRI FORD, INFINITI, KIA 0280130058, 6PT009107-441</p>	<p>09.33150</p>  <p>SENSOR TEMP LÍQ REFRI FIAT, LANCIA 0280130066, 0824121077</p>	<p>09.33155</p>  <p>SENSOR TEMP LÍQ REFRI BMW, LAND ROVER, MG 6PT009107-101, 55478</p>	<p>09.33190</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, FIAT, LANCIA 6PT009309-0171, 7.3204</p>
<p>09.33200</p>  <p>SENSOR TEMP LÍQ REFRI ALFA ROMEO 6PT 009 309-291, S103074001A</p>	<p>09.33250</p>  <p>SENSOR TEMP LÍQ REFRI JAGUAR, LEXUS, MAZDA 179700-0140, 0824121116</p>	<p>09.33260</p>  <p>SENSOR TEMP LÍQ REFRI FORD, MAZDA 6PT009107-451, 0824121074</p>	<p>09.33280</p>  <p>SENSOR TEMP LÍQ REFRI MERCEDES 6PT 009107-491, 0824 121 040</p>
<p>09.33290</p>  <p>SENSOR TEMP LÍQ REFRI MERCEDES 0824121020, 6PT009107-751</p>	<p>09.33310</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, DAIHATSU 179700-0230, 6PT009107-121</p>	<p>09.33311</p>  <p>SENSOR TEMP LÍQ REFRI MITSUBISHI ME202053</p>	<p>09.33320</p>  <p>SENSOR TEMP LÍQ REFRI CHEVROLET 96815490, S101539001</p>







225180724

232450042

### Gestão de Motor

### Sensores de Temperatura do Líquido de Refrigeração



<p>09.33330</p>  <p><b>SENSOR TEMP LÍQ REFRI ALFA ROMEO, FIAT, OPEL</b> 0280130009, 6PT009107-271</p>	<p>09.33340</p>  <p><b>SENSOR TEMP LÍQ REFRI BUICK, CADILLAC, DAEWOO, GEO</b> 0824121117, 6PT009107-591</p>	<p>09.33350</p>  <p><b>SENSOR TEMP LÍQ REFRI HYUNDAI, KIA, OPEL</b> 0824121114, 6PT009107-411</p>	<p>09.33355</p>  <p><b>SENSOR TEMP LÍQ REFRI FORD, HYUNDAI, KIA</b> J5620301, 55548</p>
<p>09.33360</p>  <p><b>SENSOR TEMP LÍQ REFRI DAIHATSU, MAZDA, SUZUKI</b> 6PT009107-521, J5653016</p>	<p>09.33410</p>  <p><b>SENSOR TEMP LÍQ REFRI AUDI</b> 0280 130 053, 55471</p>	<p>09.33425</p>  <p><b>SENSOR TEMP LÍQ REFRI JAGUAR, MAZDA VOLVO, FORD</b> 0824121188, 55508</p>	<p>09.33430</p>  <p><b>SENSOR TEMP LÍQ REFRI FORD, MAZDA, NISSAN</b> 0824121076, 55507</p>
<p>09.33450</p>  <p><b>SENSOR TEMP LÍQ REFRI ACURA, HONDA, ROVER</b> 6PT009107-511, J5624002</p>	<p>09.33460</p>  <p><b>SENSOR TEMP LÍQ REFRI FORD, INFINITI, NISSAN, OPEL</b> 0280130081, 0280130081</p>	<p>09.33480</p>  <p><b>SENSOR TEMP LÍQ REFRI OPEL, VAUXHALL</b> 0281002169, 90541937</p>	<p>09.33485</p>  <p><b>SENSOR TEMP LÍQ REFRI CITROEN, FERRARI, MASERATI</b> 0281002170, 0281002473</p>
<p>09.33490</p>  <p><b>SENSOR TEMP LÍQ REFRI ALFA ROMEO, FIAT, HONDA, LANCIA</b> 0280130093, 82017881</p>	<p>09.33540</p>  <p><b>SENSOR TEMP LÍQ REFRI DODGE, JEEP</b> 56004815, 4723860</p>	<p>09.33555</p>  <p><b>SENSOR TEMP LÍQ REFRI OPEL, VAUXHALL</b> 6PT009107-721, 52975</p>	<p>09.33570</p>  <p><b>SENSOR TEMP LÍQ REFRI DAIHATSU</b> 55133, 7.3212</p>
<p>09.33595</p>  <p><b>SENSOR TEMP LÍQ REFRI JAGUAR, LAND ROVER, LOTUS</b> 55522, 7.3248</p>	<p>09.33600</p>  <p><b>SENSOR TEMP LÍQ REFRI ALFA ROMEO, BMW, FIAT, FORD, JEEP</b> 0280130055, 55520</p>	<p>09.33610</p>  <p><b>SENSOR TEMP LÍQ REFRI VOLKSWAGEN</b> 251919501, TS-367</p>	<p>09.33620</p>  <p><b>SENSOR TEMP LÍQ REFRI AUDI, FORD, SEAT, VW</b> 6PT009107-241, 7.3086</p>
<p>09.33630</p>  <p><b>SENSOR TEMP LÍQ REFRI AUDI, FORD, SEAT, SKODA</b> 6PT009107-551, 323-805-013-001</p>	<p>09.33640</p>  <p><b>SENSOR TEMP LÍQ REFRI FORD, SEAT, SKODA, VW</b> 6PT009107-421, 824121081</p>	<p>09.33650</p>  <p><b>SENSOR TEMP LÍQ REFRI SEAT, SKODA, VW</b> 0824121082, 6PT009107-461</p>	<p>09.33660</p>  <p><b>SENSOR TEMP LÍQ REFRI CITROEN, FIAT, PEUGEOT</b> 335109.01, 9563138080</p>



225180724

232450042

### Gestão de Motor

### Sensores de Temperatura do Líquido de Refrigeração



<p>09.33690</p>  <p>SENSOR TEMP LÍQ REFRI OPEL, VAUXHALL 0281002259, 09117449</p>	<p>09.33700</p>  <p>SENSOR TEMP LÍQ REFRI ALFA ROMEO, FIAT, FORD 510040224602, 55143</p>	<p>09.33704</p>  <p>SENSOR TEMP LÍQ REFRI ABARTH, FIAT, FORD 55190792,55190791</p>	<p>09.33705</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, FIAT, LANCIA 0986280404, 0824121259</p>
<p>09.33706</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, FIAT 269414, TS10277</p>	<p>09.33707</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, PEUGEOT 6PT009309-221, 7.3328</p>	<p>09.33710</p>  <p>SENSOR TEMP LÍQ REFRI FIAT 40224603, 46520384</p>	<p>09.33720</p>  <p>SENSOR TEMP LÍQ REFRI ALFA ROMEO, FIAT 46474712, 46474713</p>
<p>09.33721</p>  <p>SENSOR TEMP LÍQ REFRI FIAT 171925011060,40216901</p>	<p>09.33723</p>  <p>SENSOR TEMP LÍQ REFRI ALFA ROMEO, FIAT 1287213610, 171925011050</p>	<p>09.33724</p>  <p>SENSOR TEMP LÍQ REFRI DACIA, NISSAN, OPEL 40211402, 226306024R</p>	<p>09.33734</p>  <p>SENSOR TEMP LÍQ REFRI FORD, JAGUAR, LAND ROVER TS-10240-12B1, LR018397</p>
<p>09.33735</p>  <p>SENSOR TEMP LÍQ REFRI JAGUR, MAZDA, VOLVO DY-824,DY-1156</p>	<p>09.33746</p>  <p>SENSOR TEMP LÍQ REFRI FORD 6PT009309-411, F65F-6G004-AB</p>	<p>09.33755</p>  <p>SENSOR TEMP LÍQ REFRI CHRYSLER, DODGE, JEEP 56027873, TX-81</p>	<p>09.33760</p>  <p>SENSOR TEMP LÍQ REFRI FIAT, LANCIA 6PT009107-571, 401930</p>
<p>09.33780</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, SKODA, SEAT, VW 078919501B</p>	<p>09.33781</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, SEAT, SKODA, VW 078919501C</p>	<p>09.33782</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, SEAT, SKODA, VW 0824121175, 6PT009107-541</p>	<p>09.33783</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, FORD, SEAT 059919501A, 059919501A</p>
<p>09.33784</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, FORD, PORSCHE 0824121168, 6PT009309-311</p>	<p>09.33785</p>  <p>SENSOR TEMP LÍQ REFRI 814/1/5, 058919501A</p>	<p>09.33790</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, FAIT, 9633518580, 1338.C0</p>	<p>09.33791</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, FIAT, PEUGEOT 9625027280, 1338.87</p>



225180724

232450042

## Gestão de Motor

### Sensores de Temperatura do Líquido de Refrigeração



<p>09.33792</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, FIAT, LANCIA TS10268, 262.051</p>	<p>09.33793</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, PEUGEOT 6PT009309-201, 7.3321</p>	<p>09.33795</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, FIAT, PEUGEOT 9636777280, TS10260</p>	<p>09.33800</p>  <p>SENSOR TEMP LÍQ REFRI HYUNDAI, MITSUBISHI 39220-21320, MD-069879</p>
<p>09.33810</p>  <p>SENSOR TEMP LÍQ REFRI DACIA, NISSAN, OPEL 95515371,9110578</p>	<p>09.33850</p>  <p>SENSOR TEMP LÍQ REFRI FIAT, LANCIA 46824133, 71719393</p>	<p>09.33860</p>  <p>SENSOR TEMP LÍQ REFRI DAEWOO, PUCH 0115425117, 2D0919369</p>	<p>09.33880</p>  <p>SENSOR TEMP LÍQ REFRI KIA, MERCEDES 7.3338, 331104X400</p>
<p>09.33890</p>  <p>SENSOR TEMP LÍQ REFRI BMW 7.3348, 89422-WA010</p>	<p>09.33910</p>  <p>SENSOR TEMP LÍQ REFRI DAIHATSU TS10183, 89422-22030</p>	<p>09.34010</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT 333281.01,333459.01</p>	<p>09.34030</p>  <p>SENSOR TEMP LÍQ REFRI LANCIA 5996648</p>
<p>09.34040</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT 7700786467</p>	<p>09.34060</p>  <p>SENSOR TEMP LÍQ REFRI ALFA ROMEO, FIAT 60806378, 7553258</p>	<p>09.34070</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT 7700805271,7700786466</p>	<p>09.34080</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN 504127558, 1338.93</p>
<p>09.34090</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN 336401.05, 9608913880</p>	<p>09.34100</p>  <p>SENSOR TEMP LÍQ REFRI RENAU 7700810879</p>	<p>09.34110</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, FIAT, PEUGEOT PEJ10007, 0242.68</p>	<p>09.34150</p>  <p>SENSOR TEMP LÍQ REFRI MERCEDES 323.803/004/007,323.803/004</p>
<p>09.34180</p>  <p>SENSOR TEMP LÍQUIDO REFRI 323.803/002/007</p>	<p>09.34200</p>  <p>SENSOR TEMP LÍQ REFRI MERCEDES 323.803/004/002</p>	<p>09.34210</p>  <p>SENSOR TEMP LÍQ REFRI EBRO, NISSAN 401096.01, 01501129-0</p>	<p>09.34220</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, VW 053919501A</p>



<p>09.34230</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT 7700805612</p>	<p>09.34290</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT 7700805266</p>	<p>09.34300</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT 7700805614</p>	<p>09.34310</p>  <p>SENSOR TEMP LÍQ REFRI MERCEDES 201.01, 0065459124</p>
<p>09.34330</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, FORD, VW 701919369C, 95VW-8B607-LA</p>	<p>09.34350</p>  <p>SENSOR TEMP LÍQ REFRI MITSUBISHI 269609, 4402298</p>	<p>09.34390</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT, VOLVO 9144143-0, 7700828565</p>	<p>09.34430</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN 9625202480, 1338.85</p>
<p>09.34440</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, PEUGEOT 336401, 0242.83</p>	<p>09.34450</p>  <p>SENSOR TEMP LÍQ REFRI OPEL, RENAULT 9160357, 7700300648</p>	<p>09.34470</p>  <p>SENSOR TEMP LÍQ REFRI NISSAN 25080-9X200</p>	<p>09.35040</p>  <p>6,35 mm</p> <p>SENSOR TEMP LÍQ REFRI RENAULT 6058, 0854805100</p>
<p>09.35070</p>  <p>SENSOR TEMP LÍQ REFRI FIAT, LANCIA, SEAT 603773, 603753</p>	<p>09.35080</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT, VOLVO 8552680, 326970.01</p>	<p>09.35090</p>  <p>6,35 mm</p> <p>SENSOR TEMP LÍQ REFRI ROVER, AUTHI 439189700.3, E1C2225</p>	<p>09.35120</p>  <p>SENSOR TEMP LÍQ REFRI SEAT, FIAT 603267, 4146350</p>
<p>09.35130</p>  <p>6,35 mm</p> <p>SENSOR TEMP LÍQ REFRI CITROEN 510094775090, 7910014016</p>	<p>09.35140</p>  <p>SENSOR TEMP LÍQ REFRI VOLVO 3100949-1</p>	<p>09.35150</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN 4129, 314740.02</p>	<p>09.35170</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN 319247.08, 325320.01</p>
<p>09.35180</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN 327122.02, 327122.03</p>	<p>09.35200</p>  <p>SENSOR TEMP LÍQ REFRI PEUGEOT, RENAULT 319247.07, 0242.32</p>	<p>09.35210</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, FIAT, FORD 307336.07, 307336.09</p>	<p>09.35220</p>  <p>SENSOR TEMP LÍQ REFRI PEUGEOT 0242.24</p>



### Gestão de Motor

### Sensores de Temperatura do Líquido de Refrigeração



<p>09.35250</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT 7700786 460, 7700823512</p>	<p>09.35290</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, HYUNDAI 337351.04, 94650-29100</p>	<p>09.35310</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, SEAT 191919369A, TS-369</p>	<p>09.35320</p>  <p>SENSOR TEMP LÍQ REFRI SEAT, SKODA, 251919369B, TS-499</p>
<p>09.35340</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, VW 053919521, 191919521B</p>	<p>09.35350</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, SEAT, SKODA, VW 191919521D, TS-223</p>	<p>09.35390</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT 7700739058</p>	<p>09.35500</p>  <p>SENSOR TEMP LÍQ REFRI ALFA ROMEO 60537203</p>
<p>09.35560</p>  <p>SENSOR TEMP LÍQ REFRI FIAT 4755799</p>	<p>09.35570</p>  <p>SENSOR TEMP LÍQ REFRI BMW, LAND ROVER STC2254, 12632243815</p>	<p>09.35580</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, SEAT, FORD, SKODA 357919369E, 357919369E</p>	<p>09.35590</p>  <p>SENSOR TEMP LÍQ REFRI FORD, SEAT, VW 701919369E, 701919369E</p>
<p>09.35610</p>  <p>SENSOR TEMP LÍQ REFRI CITROEN, FIAT, PEUGEOT 0824121214, 401044.01</p>	<p>09.35640</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, FORD, SEAT, VW</p>	<p>09.35660</p>  <p>SENSOR TEMP LÍQ REFRI AUDI, VW</p>	<p>09.35670</p>  <p>SENSOR TEMP LÍQ REFRI SUZUKI 95573-60A50</p>
<p>09.35700</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT 7700790581</p>	<p>09.35720</p>  <p>SENSOR TEMP LÍQ REFRI RENAULT 7700260972</p>	<p>09.35770</p>  <p>SENSOR TEMP LÍQ REFRI MERCEDES-BENZ, PUCH 8.185.11, 0065453924</p>	<p>09.35790</p>  <p>SENSOR TEMP LÍQ REFRI OPEL, VAUXHALL 97081229, 1338453</p>
<p>09.35820</p>  <p>SENSOR TEMP LÍQ REFRI VW 251919521</p>	<p>09.35855</p>  <p>SENSOR TEMP LÍQ REFRI FIAT 46409675</p>		